

Miscellaneous Part Numbers for Replacement Parts

Electrical

Mast Light Bulb: Perko #SDL4410321

Deck Mount Bow Lights: Green – Perko 963 G00 CHR (full assembly)

Red – Perko 963 R00 CHR (full assembly)

Set – Perko 963 DP CHR

Bulb: Perko # FIG.71

Yanmar 2GM20F Engine

Oil Filter: Yanmar #119660-35150

Sea Water Pump Impeller: Yanmar #124223-42092

Impeller Gasket: Yanmar #124223-42110

Impeller Cover: Yanmar #121575-42150

Alternator V-Belt: 25132-003700

Water Pump Belt: 104511-78780

Engine Stop Cable: Yanmar #104271-67550

Roller Furling

Model #MKIII Unit-1

Harken direct phone # - 262-691-3320

Spare fastener set – Harken #HFG-634

Lock Screws (2) on the top of Torque Tube – Harken #HFS-333

Mounting Screws (3) on bottom of Torque Tube – Harken #HFS-334

Plastic Spool Assembly – Harken #HFG601

Headstay adjustment instructions: www.harken.com/furling/j105-furl-install.php

Pulpit and Pushpit Source

Tops In Quality, Inc.

314 E. Huron Blvd.

P.O. Box 148

Marysville, MI 48040

Tel: 810-364-7150

Fax: 810-364-7925

Email: tiq@topsinquality.com

Stanchions

Garhauer Part No. ST-TT

www.garhauermarine.com/catalog_process.cfm?cid=44

Garhauer Marine

1082 Ninth St.

Upland, CA. 91786

909-985-7513

909-946-6194

Barient Winches

Available from Arco in Australia

Email: winches@ibm.net

Web: www.arco-winch.com

Raymarine www.raymarine.com 800-539-5539

Wind Transducers: Part #R28170. This is the new style but is compatible with old ST-60 style. List price \$315.00. Available for \$277.00 from dealers.

Wind Transducer Cable (30m) – A28162 List price is \$102.00.

Note: The new transducer has gold plated contacts and the old style has tin. This difference makes it wise to replace both the connector assembly and the transducer as a pair. Otherwise the connection will eventually be unreliable.

Rudder Bearings – PYI, Seattle, WA. 800-523-7558 List \$1753.00 Wholesale \$1227.10

Harken Traveler Parts for conversion from windward car.

2 – H150 Cam Cleats or recycle old cleats from windward mechanism

2 – H137 Large fair leads

2 – H295 Flat risers for cam cleats

2 – H1515 double sheaves to replace windward car sheaves.

Fuel Tank: RDS Manufacturing Inc., Florida, (850) 584-6898, Part# 62194, \$372.00 plus shipping. Comes with fuel gauge and painted with primer.

Head Door Hinges: <http://www.marinedoorandcabinhardware.com/hinges.htm>

Part # 4546-L-MPCH 386-943-8857

Winches: Primary – Harken 44.2AST or Lewmar 44AST

Secondary – Harken 33.2AST or Lewmar 33AST

Schaefer Lead Block Sheaves: Part # 62-019-02B